#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee:

Paul E. Doucette et al.

U.S. Patent No.:

US 7,079,588 B1

Issue Date:

July 18, 2006

Serial No.:

10/028,009

Filing Date:

December 21, 2001

Confirmation No.:

2368

Title:

METHOD AND APPARATUS FOR PROCESSING SIGNALS IN

AN ARRAY ANTENNA SYSTEM

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR § 1.322

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted, BAKER BOTTS L.L.P. Attorneys for Applicants

Bradley P. Williams

Date: 5/30/08

Customer No.: 45507 Phone: (214) 953-6447

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.: US 7,079,588 B1 Dated: July 18, 2006

Inventor(s): Paul E. Doucette et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### Title Page:

Page 2, Right Column, Line 5, after "GPS/"please delete "GLONASSS" and insert -- GLONASS --.

### Column 9, Line 16:

After "phase shift" delete "01" and insert -- ø1--.

Mailing Address of Sender:

Baker Botts L.L.P. 2001 Ross Avenue, Suite 600 Dallas, Texas 75201-2980 Patent No. US 7,079,588 B1

Form PTO-1050